600 Thilmany Road Kaukauna, WI 54130

Mark Nessmann
Environmental Manager
P 920-766-8235
Mark.Nessmann@experaspecialty.com

April 22, 2016

Ms. Michelle Farley
Air Engineer
Department of Natural Resources
2984 Shawano Avenue
Green Bay, Wisconsin 54313-6727

Mr. Manoj Patel
Environmental Engineer
Air Enforcement and Compliance Assurance Branch (MI/WI)
US Environmental Protection Agency
Air and Radiation Division, Region 5
77 W. Jackson Blvd. AE-17J
Chicago, IL. 60604

**RE: 1st Q 2016 Excess Emissions, CMS Performance and Periodic SSM Reports for Sources Regulated by 40 CFR 63 Subpart MM for Expera Specialty-Thilmany Mill**

Dear Michelle and Manoj:

The Expera Specialty- Thilmany Mill is subject to the reporting requirements specified by the NESHAP promulgated at 40 CFR 63 Subpart MM. This report meets the requirements for submitting an Excess Emissions, CMS Performance, and Periodic SSM Reports pursuant to 40 CFR.63.10(d)(5); 40 CFR 63.10(e)(3), and 40 CFR 63.867 (c).

This report covers the period January 1 - March 31, 2016 for the Lime Kiln, Smelt Dissolving Tanks and Recovery Boilers.

If you have any questions concerning the information on these reports, please contact me at (920) 766-8235.

Sincerely,

Mark Nessmann
Environmental Manager

EXPERA specialty solutions™

# COMPLIANCE REPORT

**for meeting reporting requirements in 40 CFR 63.10(d)(5), 63.10(e)(3) and applicable standard**

## General Information

| | |
|---|---|
| **Facility Identification** Name: | **Expera Specialty Solutions - Thilmany Mill** |
| Address: | **600 Thilmany Road** |
| City: | **Kaukauna** State: **Wisconsin** Zip: **54130** |
| **End of Reporting Period** | 3/31/2016 |
| **Relevant standard that is the basis for this report** | Chemical Recovery Combustion Sources NESHAP - Subpart MM, §63.860 |
| **Process units covered by this report** | - Recovery Furnaces B08, B10<br>- Smelt Dissolving Tanks SDT 8, SDT 10<br>- Lime Kiln |
| **Reports submitted for each process unit** | - Emission Data Summary §63.10(e)(3)(vi)<br>- CMS Performance Summary §63.10(e)(3)(vi)<br>- Emission Data Detail for SSM Events and Other Events §63.867(c), §63.10(c), 63.10(d)(5)(i)<br>- CMS Performance Detail for Downtime Events §63.867(c), §63.10(c), 63.10(d)(5)(i) |

**Were any changes made to the SSM plan since the last reporting period?** §63.6(e)(3)(viii)

No [X] Yes [ ] If yes, superceded versions are maintained on site in accordance with 40 CFR 63.6(e)(3)(v).

**Were there any changes in CMS, processes, or controls since the last reporting period?** §63.10(e)(3)(vi)(K)

No [X] Yes [ ] If yes, describe below or a separate page.

Notes/Comments:

**Certification**

***Based on information and belief formed after reasonable inquiry, I certify, to the best of my knowledge, that the statements and information in this submission are true, accurate, and complete.***

Name Mark Nessmann Title Environmental Manager

Signature Mark Nessmann Report Date 4/22/16

Version 08.12.2003.16.05

EXPERA specialty solutions™

# Continuous Monitoring System Equipment List

**Report Run Date**

**End Of Reporting Period:** 3/31/2016 4/21/2016 11:00

**Relevant standard that is the basis for this report:** Chemical Recovery Combustion Sources NESHAP - Subpart MM, §63.860

| Emission Point | Monitoring Equipment | CMS Manufacturer | CMS Model No. | Date of Latest Certification or Audit* |
|---|---|---|---|---|
| B08 and B10 - A Stack | COMS | Durag | D-R 290 | March 29, 2016 |
| B08 and B10 - B Stack | COMS | Durag | D-R 290 | March 29, 2016 |
| SDT8 | Differential Pressure | ABB | 600T-EN | July 29, 2015 |
| SDT8 | Scrubber Water Flow | Krohne | IFC-080/ F / MP | July 29, 2015 |
| SDT10 | Differential Pressure | ABB | 600T-EN | July 29, 2015 |
| SDT10 | Scrubber Water Flow | Yokogawa | AM-11-DEA1A | July 29, 2015 |
| Lime Kiln | Ahlstrom Scrubber Flow | Foxboro | 8003A-WCR-PJG-FNA-A | July 13, 2015 |
| Lime Kiln | Ahlstrom Scrubber Pressure | Bailey | PTPGP72020E | July 13, 2015 |
| Lime Kiln | Turbotak Air Pressure | Foxboro | 821GM-IS1NM2 | July 9, 2015 |
| Lime Kiln | Turbotak Water Flow | ABB | 10DX3111EDE | July 9, 2015 |

=cell[a1:a1].value

EXPERA specialty solutions™

# SUMMARY REPORT - Gaseous and Opacity Excess Emissions

**Thilmany Mill** — **Lime Kiln**

**Reporting Period:** **From** 1/1/2016 — **To** 4/1/2016

**Report Run Date** 4/21/2016 8:47 AM

| | |
|---|---|
| **Hazardous Air Pollutants (HAPS) Monitored:** | Particulate Matter (PM) emissions as a surrogate for HAP metals (Subpart MM, §63.860). |
| **Brief description of process unit:** | Calcium Carbonate (Lime Mud) is calcined in the Lime Kiln producing Calcium Oxide. PM emissions are controlled by the Ahlstrom scrubber and the Turbotak scrubbing components. |

## Emission Data Summary

| | LK Ahlstrom | | | | LK Turbotak | | | |
|---|---|---|---|---|---|---|---|---|
| **Emission Point:** | | | | | | | | |
| **Source Operating Time:** | 2,182.9 | | | | 2136.6 | | | |
| **Operating Parameter:** | Flow | | Pressure | | Flow | | Pressure | |
| **Averaging Period:** | 3-hr Avg | | 3-hr Avg | | 3-hr Avg | | 3-hr Avg | |
| **Parameter Limit:** | 276.6 gpm | | 267.5 PSI | | 44.1 gpm | | 96.4 PSI | |
| **Monitoring Exceedances In Reporting Period Due To:** | Duration Hours | Count No. | Duration Hours | Count No. | Duration Hours | Count No. | Duration Hours | Count No. |
| **a. Startup/Shutdown** | 0.0 | 0 | 0.0 | 0 | 0.0 | 0 | 0.0 | 0 |
| **b. Control Equipment Problems-Malfunction** | 0.0 | 0 | 0.0 | 0 | 0.0 | 0 | 0.0 | 0 |
| **c. Process Problems-Malfunction** | 0.0 | 0 | 0.0 | 0 | 0.0 | 0 | 0.0 | 0 |
| Total SSM monitoring exceedances | 0.0 | 0 | 0.0 | 0 | 0.0 | 0 | 0.0 | 0 |
| **d. Other Known Causes** | 0.0 | 0 | 0.0 | 0 | 0.0 | 0 | 0.0 | 0 |
| **e. Other Unknown Causes** | 0.0 | 0 | 0.0 | 0 | 0.0 | 0 | 0.0 | 0 |
| Total Other monitoring exceedances | 0.0 | 0 | 0.0 | 0 | 0.0 | 0 | 0.0 | 0 |
| [(Total Other monitoring exceedances)/(Total source operating time)]X100 (%) | 0.00% | | 0.00% | | 0.00% | | 0.00% | |
| Total monitoring exceedances | 0.0 | 0 | 0.0 | 0 | 0.0 | 0 | 0.0 | 0 |
| [(Total monitoring exceedances)/(Total source operating time)]X100 (%) | 0.00% | | 0.00% | | 0.00% | | 0.00% | |
| Number of 24 hour periods with one or more non-SSM monitoring exceedances | 0 | | | | | | | |

Footnote 1 for, "Startup/Shutdown, Control Equipment Problems, and Process Problems": Except for actions which may have been previously reported according to 40 CFR 63.10(d)(5)(ii), actions taken in response to SSM events were consistent with the procedures specified in the SSM plan required by 40 CFR 63.6(e)(3). These actions were documented pursuant to 40 CFR 63.6(e)(3)(iii) and reported per 40 CFR 63.10(d)(5)(i).

Footnote 2 for, "Number of 24-hour periods with one or more non-SSM monitoring exceedances": Periods of excess emission are not a violation of 40 CFR 63.862 provided the number of 3-hour parameter exceedances is not 6 or greater during the source operating time within a semi-annual period per 40 CFR 63.864(k)(2)(iii), excluding periods of startup, shutdown and malfunction [40 CFR 63.6(f)(1)]. No more than one exceedance shall be attributed to any 24-hour period per 40 CFR 63.864(k)(3).

EXPERA specialty solutions™

## DETAIL REPORT - Gaseous and Opacity Excess Emissions

**Thilmany Mill** | **Lime Kiln** | **Report Run Date:** 4/21/2016 8:47 AM

**Reporting Period:** **From** 1/1/2016 **To** 4/1/2016

### Emission Data Detail for SSM Events and Other Events

| Start Time | End Time | Duration (Hours) | Location | Trouble | Cause | Correction | Report Code |
|---|---|---|---|---|---|---|---|
| | Lime Kiln | | | | | | |
| | | | LK1 Ahlstrom Flow EE | No Events | | | |
| | | | LK1 Ahlstrom Pressure EE | No Events | | | |
| | | | LK1 Turbotak Flow EE | No Events | | | |
| | | | LK1 Turbotak Pressure EE | No Events | | | |

EXPERA specialty solutions™

# SUMMARY REPORT - Continuous Monitoring System Performance

**Thilmany Mill** — **Lime Kiln**

**Reporting Period:** From 1/1/2016 To 4/1/2016

**Report Run Date** 4/21/2016 8:47 AM

## CMS Performance Summary

| | Emission Point: | LK | | | | | | |
|---|---|---|---|---|---|---|---|---|
| | Source Operating Time: | 2182.9 Hours | | | | | | |
| | Monitoring Equipment: | Ahlstrom Flow | | Ahlstrom Pressure | | Turbotak Flow | | Turbotak Pressure | |
| **CMS Downtime In Reporting Period Due To:** | | Duration Hours | Count No. | Duration Hours | Count No. | Duration Hours | Count No. | Duration Hours | Count No. |
| **a. Monitor Equipment Malfunctions** | | 0.0 | 0 | 0.0 | 0 | 0.0 | 0 | 0.0 | 0 |
| **b. Non-Monitor Equipment Malfunctions** | | 0.0 | 0 | 0.0 | 0 | 0.0 | 0 | 0.0 | 0 |
| **c. Quality Assurance/Quality Control Calibrations** | | 0.0 | 0 | 0.0 | 0 | 0.0 | 0 | 0.0 | 0 |
| Total malfunctions & QA/QC calibrations | | 0.0 | 0 | 0.0 | 0 | 0.0 | 0 | 0.0 | 0 |
| **d. Other Known Causes** | | 0.0 | 0 | 0.0 | 0 | 0.0 | 0 | 0.0 | 0 |
| **e. Other Unknown Causes** | | 0.0 | 0 | 0.0 | 0 | 0.0 | 0 | 0.0 | 0 |
| Total Other causes | | 0.0 | 0 | 0.0 | 0 | 0.0 | 0 | 0.0 | 0 |
| Total CMS downtime | | 0.0 | 0 | 0.0 | 0 | 0.0 | 0 | 0.0 | 0 |
| [(Total CMS downtime)/(Total source operating time)]X100 (%) | | 0.00% | | 0.00% | | 0.00% | | 0.00% | |

Footnote 1 for, "Monitor Equipment Malfunctions, Non-Monitor Equipment Malfunctions, and Quality Assurance/Quality Control Calibrations": Except for actions which may have been previously reported according to 40 CFR 63.10(d)(5)(ii), actions taken in response to SSM events were consistent with the procedures specified in the SSM plan required by 40 CFR 63.6(e)(3). These actions were documented pursuant to 40 CFR 63.6(e)(3)(iii) and reported per 40 CFR 63.10(d)(5)(i).

EXPERA specialty solutions™

# DETAIL REPORT - Continuous Monitoring System Performance

**Thilmany Mill** | **Lime Kiln** | **Report Run Date:** 4/21/2016 8:47 AM

**Reporting Period:** From 1/1/2016 To 4/1/2016

## CMS Performance Detail for SSM Events and Other Events

| Start Time | End Time | Duration (Hours) | Location | Trouble | Cause | Correction | Report Code |
|---|---|---|---|---|---|---|---|
| | | | **Lime Kiln** | | | | |
| | | | LK1 Ahlstrom Flow CMS | No Events | | | |
| | | | LK1 Ahlstrom Pressure CMS | No Events | | | |
| | | | LK1 Turbotak Flow CMS | No Events | | | |
| | | | LK1 Turbotak Pressure CMS | No Events | | | |

EXPERA specialty solutions™

# SUMMARY REPORT - Gaseous and Opacity Excess Emissions

## Thilmany Mill

## Recovery Furnace 8-10

**Reporting Period:** From 1/1/2016 To 4/1/2016

**Report Run Date:** 4/21/2016 8:48 AM

| | |
|---|---|
| **Hazardous Air Pollutants (HAPS) Monitored:** | Particulate Matter (PM) emissions as a surrogate for HAP metals (Subpart MM, §63.860). |
| **Brief description of process unit:** | No. 8 and No. 10 Recovery Furnaces are non-direct contact, low-odor steam generating units firing black liquor. The exhaust gases combine and are treated in parallel by two 3-field precipitators (A&B). |

**Emission Data Summary**

| | RF 8-10A | | | | RF 8-10B | | | |
|---|---|---|---|---|---|---|---|---|
| **Emission Point:** | | | | | | | | |
| **Source Operating Time:** | 2,173.9 | | | | 2168.2 | | | |
| **Operating Parameter:** | Opacity | | Opacity | | Opacity | | Opacity | |
| **Averaging Period:** | 6-min Avg | | 60-min Avg | | 6-min Avg | | 60-min Avg | |
| **Parameter Limit:** | 35% | | 20% | | 35% | | 20% | |
| **Monitoring Exceedances In Reporting Period Due To:** | Duration Hours | Count No. | Duration Hours | Count No. | Duration Hours | Count No. | Duration Hours | Count No. |
| **a. Startup/Shutdown** | 0.0 | 0 | 0.0 | 0 | 0.0 | 0 | 0.0 | 0 |
| **b. Control Equipment Problems-Malfunction** | 0.0 | 0 | 0.0 | 0 | 0.0 | 0 | 0.0 | 0 |
| **c. Process Problems-Malfunction** | 0.0 | 0 | 0.0 | 0 | 0.0 | 0 | 0.0 | 0 |
| Total SSM monitoring exceedances | 0.0 | 0 | 0.0 | 0 | 0.0 | 0 | 0.0 | 0 |
| **d. Other Known Causes** | 0.0 | 0 | 0.0 | 0 | 0.0 | 0 | 0.0 | 0 |
| **e. Other Unknown Causes** | 0.0 | 0 | 0.0 | 0 | 0.0 | 0 | 0.0 | 0 |
| Total Other monitoring exceedances | 0.0 | 0 | 0.0 | 0 | 0.0 | 0 | 0.0 | 0 |
| [(Total Other monitoring exceedances)/(Total source operating time)]X100 (%) | 0.00% | | 0.00% | | 0.00% | | 0.00% | |
| Total monitoring exceedances | 0.0 | 0 | 0.0 | 0 | 0.0 | 0 | 0.0 | 0 |
| [(Total monitoring exceedances)/(Total source operating time)]X100 (%) | 0.00% | | 0.00% | | 0.00% | | 0.00% | |

Footnote 1 for, "Startup/Shutdown, Control Equipment Problems, and Process Problems": Except for actions which may have been previously reported according to 40 CFR 63.10(d)(5)(ii), actions taken in response to SSM events were consistent with the procedures specified in the SSM plan required by 40 CFR 63.6(e)(3). These actions were documented pursuant to 40 CFR 63.6(e)(3)(iii) and reported per 40 CFR 63.10(d)(5)(i).

Footnote 2 for, "[(Total Other monitoring exceedances)/(Total source operating time)]X100 (%)": Periods of excess emissions are not a violation of 40 CFR 63.862 provided that opacity does not exceed 35% for 6 percent or more of the source operating time within a quarterly period per 40 CFR 63.864(k)(2)(i), excluding periods of startup, shutdown and malfunction [40 CFR 63.6(h)(1)].

EXPERA specialty solutions™

## DETAIL REPORT - Gaseous and Opacity Excess Emissions

**Thilmany Mill** | **Recovery Furnace 8-10** | **Report Run Date:** 4/21/2016 8:48 AM

**Reporting Period:** From 1/1/2016 To 4/1/2016

### Emission Data Detail for SSM Events and Other Events

| Start Time | End Time | Duration (Hours) | Location | Trouble | Cause | Correction | Report Code |
|---|---|---|---|---|---|---|---|
| **Recovery Furnace 8-10** | | | | | | | |
| | | | RF8-10A Opacity EE (6-Min) | No Events | | | |
| | | | RF8-10A Opacity EE (60-Min) | No Events | | | |
| | | | RF8-10B Opacity EE (6-Min) | No Events | | | |
| | | | RF8-10B Opacity EE (60-Min) | No Events | | | |

EXPERA specialty solutions™

# SUMMARY REPORT - Continuous Monitoring System Performance

**Thilmany Mill** — **Recovery Furnace 8-10**

**Reporting Period:** **From** 1/1/2016 — **To** 4/1/2016

**Report Run Date** 4/21/2016 8:48 AM

| **CMS Performance Summary** | **Emission Point:** | RF 8-10A | | RF 8-10B | |
|---|---|---|---|---|---|
| | **Source Operating Time:** | 2173.9 | | 2168.2 | |
| | **Monitoring Equipment:** | Opacity | | Opacity | |
| **CMS Downtime In Reporting Period Due To:** | | Duration | Count | Duration | Count |
| | | Hours | No. | Hours | No. |
| **a. Monitor Equipment Malfunctions** | | 0.0 | 0 | 0.0 | 0 |
| **b. Non-Monitor Equipment Malfunctions** | | 0.0 | 0 | 0.0 | 0 |
| **c. Quality Assurance/Quality Control Calibrations** | | 10.6 | 92 | 10.6 | 92 |
| Total malfunctions & QA/QC calibrations | | 10.6 | 92 | 10.6 | 92 |
| **d. Other Known Causes** | | 0.0 | 0 | 0.0 | 0 |
| **e. Other Unknown Causes** | | 0.0 | 0 | 0.0 | 0 |
| Total Other causes | | 0.0 | 0 | 0.0 | 0 |
| Total CMS downtime | | 10.6 | 92 | 10.6 | 92 |
| [(Total CMS downtime)/(Total source operating time)]X100 (%) | | 0.49% | | 0.49% | |

Footnote 1 for, "Monitor Equipment Malfunctions, Non-Monitor Equipment Malfunctions, and Quality Assurance/Quality Control Calibrations": Except for actions which may have been previously reported according to 40 CFR 63.10(d)(5)(ii), actions taken in response to SSM events were consistent with the procedures specified in the SSM plan required by 40 CFR 63.6(e)(3). These actions were documented pursuant to 40 CFR 63.6(e)(3)(iii) and reported per 40 CFR 63.10(d)(5)(i).

EXPERA specialty solutions

# DETAIL REPORT - Continuous Monitoring System Performance

**Thilmany Mill** | **Recovery Furnace 8-10** | **Report Run Date:** 4/21/2016 8:48 AM

**Reporting Period:** **From** 1/1/2016 **To** 4/1/2016

## CMS Performance Detail for SSM Events and Other Events

| Start Time | End Time | Duration (Hours) | Location | Trouble | Cause | Correction | Report Code |
|---|---|---|---|---|---|---|---|
| | **Recovery Furnace 8-10** | | | | | | |
| 1/2/2016 3:07 AM | 1/2/2016 3:13 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/3/2016 3:07 AM | 1/3/2016 3:13 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/4/2016 3:07 AM | 1/4/2016 3:13 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/5/2016 3:07 AM | 1/5/2016 3:13 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/6/2016 3:07 AM | 1/6/2016 3:13 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/7/2016 3:07 AM | 1/7/2016 3:13 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/8/2016 3:07 AM | 1/8/2016 3:13 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/9/2016 3:07 AM | 1/9/2016 3:13 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/10/2016 3:07 AM | 1/10/2016 3:13 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/11/2016 3:07 AM | 1/11/2016 3:13 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/12/2016 3:07 AM | 1/12/2016 3:13 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/13/2016 3:07 AM | 1/13/2016 3:13 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/14/2016 3:07 AM | 1/14/2016 3:13 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/15/2016 3:07 AM | 1/15/2016 3:13 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/16/2016 3:07 AM | 1/16/2016 3:13 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/17/2016 3:07 AM | 1/17/2016 3:13 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/18/2016 3:07 AM | 1/18/2016 3:13 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/19/2016 3:07 AM | 1/19/2016 3:13 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/20/2016 3:07 AM | 1/20/2016 3:13 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/21/2016 3:07 AM | 1/21/2016 3:13 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/22/2016 3:07 AM | 1/22/2016 3:13 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/23/2016 3:07 AM | 1/23/2016 3:13 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/24/2016 3:07 AM | 1/24/2016 3:13 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/25/2016 3:07 AM | 1/25/2016 3:13 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/26/2016 3:07 AM | 1/26/2016 3:13 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/27/2016 3:07 AM | 1/27/2016 3:13 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/28/2016 3:07 AM | 1/28/2016 3:13 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/29/2016 3:07 AM | 1/29/2016 3:13 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/30/2016 3:07 AM | 1/30/2016 3:13 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/31/2016 3:07 AM | 1/31/2016 3:13 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/1/2016 3:07 AM | 2/1/2016 3:13 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/2/2016 3:07 AM | 2/2/2016 3:13 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/3/2016 3:11 AM | 2/3/2016 3:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/4/2016 3:11 AM | 2/4/2016 3:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/5/2016 3:07 AM | 2/5/2016 3:13 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/6/2016 3:11 AM | 2/6/2016 3:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/7/2016 3:11 AM | 2/7/2016 3:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/8/2016 3:11 AM | 2/8/2016 3:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/9/2016 3:11 AM | 2/9/2016 3:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/10/2016 3:11 AM | 2/10/2016 3:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/11/2016 3:11 AM | 2/11/2016 3:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/12/2016 3:11 AM | 2/12/2016 3:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/13/2016 3:11 AM | 2/13/2016 3:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/14/2016 3:11 AM | 2/14/2016 3:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/15/2016 3:11 AM | 2/15/2016 3:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/16/2016 3:11 AM | 2/16/2016 3:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/17/2016 3:11 AM | 2/17/2016 3:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/18/2016 3:11 AM | 2/18/2016 3:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/19/2016 3:11 AM | 2/19/2016 3:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/20/2016 3:11 AM | 2/20/2016 3:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/21/2016 3:11 AM | 2/21/2016 3:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/22/2016 3:11 AM | 2/22/2016 3:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/23/2016 3:11 AM | 2/23/2016 3:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/24/2016 3:11 AM | 2/24/2016 3:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/25/2016 3:11 AM | 2/25/2016 3:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |

EXPERA specialty solutions

## DETAIL REPORT - Continuous Monitoring System Performance

**Thilmany Mill** | **Recovery Furnace 8-10** | **Report Run Date:** 4/21/2016 8:48 AM

**Reporting Period:** From 1/1/2016 To 4/1/2016

### CMS Performance Detail for SSM Events and Other Events

| Start Time | End Time | Duration (Hours) | Location | Trouble | Cause | Correction | Report Code |
|---|---|---|---|---|---|---|---|
| 2/26/2016 3:11 AM | 2/26/2016 3:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/27/2016 3:11 AM | 2/27/2016 3:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/28/2016 3:11 AM | 2/28/2016 3:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/29/2016 3:11 AM | 2/29/2016 3:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/1/2016 3:11 AM | 3/1/2016 3:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/2/2016 3:11 AM | 3/2/2016 3:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/3/2016 3:11 AM | 3/3/2016 3:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/4/2016 3:11 AM | 3/4/2016 3:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/5/2016 3:11 AM | 3/5/2016 3:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/6/2016 3:11 AM | 3/6/2016 3:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/7/2016 3:11 AM | 3/7/2016 3:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/8/2016 3:11 AM | 3/8/2016 3:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/9/2016 3:11 AM | 3/9/2016 3:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/10/2016 3:11 AM | 3/10/2016 3:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/11/2016 3:11 AM | 3/11/2016 3:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/12/2016 3:11 AM | 3/12/2016 3:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/13/2016 4:11 AM | 3/13/2016 4:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/14/2016 4:11 AM | 3/14/2016 4:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/15/2016 4:11 AM | 3/15/2016 4:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/16/2016 4:11 AM | 3/16/2016 4:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/17/2016 4:11 AM | 3/17/2016 4:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/18/2016 4:11 AM | 3/18/2016 4:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/19/2016 4:11 AM | 3/19/2016 4:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/20/2016 4:11 AM | 3/20/2016 4:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/21/2016 4:11 AM | 3/21/2016 4:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/22/2016 4:11 AM | 3/22/2016 4:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/23/2016 4:11 AM | 3/23/2016 4:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/24/2016 4:11 AM | 3/24/2016 4:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/25/2016 4:11 AM | 3/25/2016 4:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/26/2016 4:11 AM | 3/26/2016 4:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/27/2016 4:11 AM | 3/27/2016 4:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/28/2016 4:11 AM | 3/28/2016 4:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/29/2016 4:11 AM | 3/29/2016 4:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/29/2016 1:00 PM | 3/29/2016 2:30 PM | 1.5 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/30/2016 4:11 AM | 3/30/2016 4:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/31/2016 4:11 AM | 3/31/2016 4:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 4/1/2016 4:11 AM | 4/1/2016 4:17 AM | 0.1 | RF8-10A Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/2/2016 3:07 AM | 1/2/2016 3:13 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/3/2016 3:07 AM | 1/3/2016 3:13 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/4/2016 3:07 AM | 1/4/2016 3:13 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/5/2016 3:07 AM | 1/5/2016 3:13 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/6/2016 3:07 AM | 1/6/2016 3:13 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/7/2016 3:07 AM | 1/7/2016 3:13 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/8/2016 3:07 AM | 1/8/2016 3:13 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/9/2016 3:07 AM | 1/9/2016 3:13 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/10/2016 3:07 AM | 1/10/2016 3:13 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/11/2016 3:07 AM | 1/11/2016 3:13 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/12/2016 3:07 AM | 1/12/2016 3:13 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/13/2016 3:07 AM | 1/13/2016 3:13 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/14/2016 3:07 AM | 1/14/2016 3:13 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/15/2016 3:07 AM | 1/15/2016 3:13 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/16/2016 3:07 AM | 1/16/2016 3:13 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/17/2016 3:07 AM | 1/17/2016 3:13 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/18/2016 3:07 AM | 1/18/2016 3:13 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/19/2016 3:07 AM | 1/19/2016 3:13 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |

EXPERA specialty solutions™

## DETAIL REPORT - Continuous Monitoring System Performance

**Thilmany Mill** | **Recovery Furnace 8-10** | **Report Run Date:** 4/21/2016 8:48 AM

**Reporting Period:** **From** 1/1/2016 **To** 4/1/2016

### CMS Performance Detail for SSM Events and Other Events

| Start Time | End Time | Duration (Hours) | Location | Trouble | Cause | Correction | Report Code |
|---|---|---|---|---|---|---|---|
| 1/20/2016 3:07 AM | 1/20/2016 3:13 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/21/2016 3:07 AM | 1/21/2016 3:13 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/22/2016 3:07 AM | 1/22/2016 3:13 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/23/2016 3:07 AM | 1/23/2016 3:13 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/24/2016 3:07 AM | 1/24/2016 3:13 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/25/2016 3:07 AM | 1/25/2016 3:13 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/26/2016 3:07 AM | 1/26/2016 3:13 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/27/2016 3:07 AM | 1/27/2016 3:13 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/28/2016 3:07 AM | 1/28/2016 3:13 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/29/2016 3:07 AM | 1/29/2016 3:13 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/30/2016 3:07 AM | 1/30/2016 3:13 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 1/31/2016 3:07 AM | 1/31/2016 3:13 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/1/2016 3:07 AM | 2/1/2016 3:13 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/2/2016 3:07 AM | 2/2/2016 3:13 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/3/2016 3:11 AM | 2/3/2016 3:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/4/2016 3:11 AM | 2/4/2016 3:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/5/2016 3:07 AM | 2/5/2016 3:13 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/6/2016 3:11 AM | 2/6/2016 3:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/7/2016 3:11 AM | 2/7/2016 3:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/8/2016 3:11 AM | 2/8/2016 3:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/9/2016 3:11 AM | 2/9/2016 3:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/10/2016 3:11 AM | 2/10/2016 3:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/11/2016 3:11 AM | 2/11/2016 3:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/12/2016 3:11 AM | 2/12/2016 3:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/13/2016 3:11 AM | 2/13/2016 3:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/14/2016 3:11 AM | 2/14/2016 3:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/15/2016 3:11 AM | 2/15/2016 3:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/16/2016 3:11 AM | 2/16/2016 3:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/17/2016 3:11 AM | 2/17/2016 3:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/18/2016 3:11 AM | 2/18/2016 3:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/19/2016 3:11 AM | 2/19/2016 3:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/20/2016 3:11 AM | 2/20/2016 3:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/21/2016 3:11 AM | 2/21/2016 3:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/22/2016 3:11 AM | 2/22/2016 3:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/23/2016 3:11 AM | 2/23/2016 3:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/24/2016 3:11 AM | 2/24/2016 3:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/25/2016 3:11 AM | 2/25/2016 3:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/26/2016 3:11 AM | 2/26/2016 3:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/27/2016 3:11 AM | 2/27/2016 3:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/28/2016 3:11 AM | 2/28/2016 3:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 2/29/2016 3:11 AM | 2/29/2016 3:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/1/2016 3:11 AM | 3/1/2016 3:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/2/2016 3:11 AM | 3/2/2016 3:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/3/2016 3:11 AM | 3/3/2016 3:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/4/2016 3:11 AM | 3/4/2016 3:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/5/2016 3:11 AM | 3/5/2016 3:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/6/2016 3:11 AM | 3/6/2016 3:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/7/2016 3:11 AM | 3/7/2016 3:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/8/2016 3:11 AM | 3/8/2016 3:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/9/2016 3:11 AM | 3/9/2016 3:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/10/2016 3:11 AM | 3/10/2016 3:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/11/2016 3:11 AM | 3/11/2016 3:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/12/2016 3:11 AM | 3/12/2016 3:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/13/2016 4:11 AM | 3/13/2016 4:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/14/2016 4:11 AM | 3/14/2016 4:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/15/2016 4:11 AM | 3/15/2016 4:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |

EXPERA specialty solutions™

## DETAIL REPORT - Continuous Monitoring System Performance

**Thilmany Mill** | **Recovery Furnace 8-10** | **Report Run Date:** 4/21/2016 8:48 AM

**Reporting Period:** From 1/1/2016 To 4/1/2016

### CMS Performance Detail for SSM Events and Other Events

| Start Time | End Time | Duration (Hours) | Location | Trouble | Cause | Correction | Report Code |
|---|---|---|---|---|---|---|---|
| 3/16/2016 4:11 AM | 3/16/2016 4:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/17/2016 4:11 AM | 3/17/2016 4:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/18/2016 4:11 AM | 3/18/2016 4:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/19/2016 4:11 AM | 3/19/2016 4:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/20/2016 4:11 AM | 3/20/2016 4:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/21/2016 4:11 AM | 3/21/2016 4:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/22/2016 4:11 AM | 3/22/2016 4:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/23/2016 4:11 AM | 3/23/2016 4:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/24/2016 4:11 AM | 3/24/2016 4:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/25/2016 4:11 AM | 3/25/2016 4:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/26/2016 4:11 AM | 3/26/2016 4:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/27/2016 4:11 AM | 3/27/2016 4:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/28/2016 4:11 AM | 3/28/2016 4:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/29/2016 4:11 AM | 3/29/2016 4:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/29/2016 1:00 PM | 3/29/2016 2:30 PM | 1.5 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/30/2016 4:11 AM | 3/30/2016 4:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 3/31/2016 4:11 AM | 3/31/2016 4:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |
| 4/1/2016 4:11 AM | 4/1/2016 4:17 AM | 0.1 | RF8-10B Opacity CMS (6-Min) | Automatic Calibration | Passed | No Action Required | QA/QC Calibrations |

EXPERA specialty solutions™

# SUMMARY REPORT - Gaseous and Opacity Excess Emissions

**Thilmany Mill** — **Recovery Furnace 8-10 Bypass**

| | | | |
|---|---|---|---|
| **Reporting Period:** | **From** | 1/1/2016 | **Report Run Date** |
| | **To** | 4/1/2016 | 4/20/2016 4:33 PM |

| | |
|---|---|
| **Hazardous Air Pollutants (HAPS) Monitored:** | Particulate Matter (PM) emissions as a surrogate for HAP metals (Subpart MM, §63.860). |
| **Brief description of process unit:** | No. 8 and No. 10 Recovery Furnaces are non-direct contact, low-odor steam generating units firing black liquor. The exhaust gases combine and are treated in parallel by two 3-field precipitators (A&B). This report documents precipitator bypass emissions. |

| **Emission Data Summary** | | |
|---|---|---|
| **Emission Point:** | RF 8-10 Bypass | |
| **Source Operating Time:** | 2168.7 Hours | |
| **Operating Parameter:** | System Bypass | |
| **Averaging Period:** | Instantaneous | |
| **Parameter Limit:** | Bypass Closed During Operation | |
| **Monitoring Exceedances In Reporting Period Due To:** | Duration<br>Hours | Count<br>No. |
| **a. Startup/Shutdown** | 0.0 | 0 |
| **b. Control Equipment Problems-Malfunction** | 0.0 | 0 |
| **c. Process Problems-Malfunction** | 0.0 | 0 |
| Total SSM monitoring exceedances | 0.0 | 0 |
| **d. Other Known Causes** | 0.0 | 0 |
| **e. Other Unknown Causes** | 0.0 | 0 |
| Total Other monitoring exceedances | 0.0 | 0 |
| [(Total Other monitoring exceedances)/(Total source operating time)]X100 (%) | 0.00% | |
| Total monitoring exceedances | 0.0 | 0 |
| [(Total monitoring exceedances)/(Total source operating time)]X100 (%) | 0.00% | |

Footnote 1 for, "Startup/Shutdown, Control Equipment Problems, and Process Problems": Except for actions which may have been previously reported according to 40 CFR 63.10(d)(5)(ii), actions taken in response to SSM events were consistent with the procedures specified in the SSM plan required by 40 CFR 63.6(e)(3). These actions were documented pursuant to 40 CFR 63.6(e)(3)(iii) and reported per 40 CFR 63.10(d)(5)(i).

EXPERA speciality solutions™

# No Excess Emission Detail Report

**Thilmany Mill** | **Recovery Furnace 8-10 Bypass** | **Report Run Date:** 4/20/2016 4:33 PM

**Reporting Period:** **From** 1/1/2016 **To** 4/1/2016

## No Excess Emission Events

| Start Time | End Time | Duration (Minutes) | Location | Trouble | Cause | Correction | Report Code |
|---|---|---|---|---|---|---|---|
| Recovery Furnace 8-10 Bypass | | | | | | | |
| | | | RF 8-10 Bypass | No Events | | | |

EXPERA specialty solutions™

# SUMMARY REPORT - Gaseous and Opacity Excess Emissions

**Thilmany Mill** — **Smelt Dissolving Tank 8**

**Reporting Period:** From 1/1/2016 To 4/1/2016

**Report Run Date:** 4/20/2016 4:34 PM

| | |
|---|---|
| **Hazardous Air Pollutants (HAPS) Monitored:** | Particulate Matter (PM) emissions as a surrogate for HAP metals (Subpart MM, §63.860). |
| **Brief description of process unit:** | Molten inorganic kraft cooking chemicals (smelt) recovered by the No. 8 Recovery Furnace are dissolved in weak wash to produce Green Liquor. PM emissions are controlled by a Turbulaire scrubber. |

## Emission Data Summary

| | | | | |
|---|---|---|---|---|
| **Emission Point:** | SDT8 | | | |
| **Source Operating Time:** | 2114.3 Hours | | | |
| **Operating Parameter:** | dP | | Flow | |
| **Averaging Period:** | 3-hr Avg | | 3-hr Avg | |
| **Parameter Limit:** | 5.0 " H2O | | 30.0 gpm | |
| **Monitoring Exceedances In Reporting Period Due To:** | Duration Hours | Count No. | Duration Hours | Count No. |
| **a. Startup/Shutdown** | 0.0 | 0 | 0.0 | 0 |
| **b. Control Equipment Problems-Malfunction** | 0.0 | 0 | 0.0 | 0 |
| **c. Process Problems-Malfunction** | 0.0 | 0 | 0.0 | 0 |
| Total SSM monitoring exceedances | 0.0 | 0 | 0.0 | 0 |
| **d. Other Known Causes** | 0.0 | 0 | 0.0 | 0 |
| **e. Other Unknown Causes** | 0.0 | 0 | 0.0 | 0 |
| Total Other monitoring exceedances | 0.0 | 0 | 0.0 | 0 |
| [(Total Other monitoring exceedances)/(Total source operating time)]X100 (%) | 0.00% | | 0.00% | |
| Total monitoring exceedances | 0.0 | 0 | 0.0 | 0 |
| [(Total monitoring exceedances)/(Total source operating time)]X100 (%) | 0.00% | | 0.00% | |
| Number of 24 hour periods with one or more non-SSM monitoring exceedances | 0 | | | |

Footnote 1 for, "Startup/Shutdown, Control Equipment Problems, and Process Problems": Except for actions which may have been previously reported according to 40 CFR 63.10(d)(5)(ii), actions taken in response to SSM events were consistent with the procedures specified in the SSM plan required by 40 CFR 63.6(e)(3). These actions were documented pursuant to 40 CFR 63.6(e)(3)(iii) and reported per 40 CFR 63.10(d)(5)(i).

Footnote 2 for, "Number of 24-hour periods with one or more non-SSM monitoring exceedances": Periods of excess emission are not a violation of 40 CFR 63.862 provided the number of 3-hour parameter exceedances is not 6 or greater during the source operating time within a semi-annual period per 40 CFR 63.864(k)(2)(iii), excluding periods of startup, shutdown and malfunction [40 CFR 63.6(f)(1)]. No more than one exceedance shall be attributed to any 24-hour period per 40 CFR 63.864(k)(3).

EXPERA specialty solutions™

# No Excess Emission Detail Report

**Thilmany Mill** — **Smelt Dissolving Tank 8** — **Report Run Date:** 4/20/2016 4:34 PM

**Reporting Period:** **From** 1/1/2016 **To** 4/1/2016

## No Excess Emission Events

| Start Time | End Time | Duration (Hours) | Location | Trouble | Cause | Correction | Report Code |
|---|---|---|---|---|---|---|---|
| **Smelt Dissolving Tank 8** | | | | | | | |
| | | | SDT8 dP EE | No Events | | | |
| | | | SDT8 Flow EE | No Events | | | |

EXPERA specialty solutions™

# SUMMARY REPORT - Continuous Monitoring System Performance

**Thilmany Mill**

## Smelt Dissolving Tank 8

**Reporting Period:** From 1/1/2016 To 4/1/2016

**Report Run Date** 4/20/2016 4:34 PM

| CMS Performance Summary | Emission Point: | SDT8 | | | |
|---|---|---|---|---|---|
| | Source Operating Time: | 2114.3 Hours | | | |
| | Monitoring Equipment: | dP | | Flow | |
| **CMS Downtime In Reporting Period Due To:** | | Duration Hours | Count No. | Duration Hours | Count No. |
| **a. Monitor Equipment Malfunctions** | | 0.0 | 0 | 0.0 | 0 |
| **b. Non-Monitor Equipment Malfunctions** | | 0.0 | 0 | 0.0 | 0 |
| **c. Quality Assurance/Quality Control Calibrations** | | 0.0 | 0 | 0.0 | 0 |
| Total malfunctions & QA/QC calibrations | | 0.0 | 0 | 0.0 | 0 |
| **d. Other Known Causes** | | 0.0 | 0 | 0.0 | 0 |
| **e. Other Unknown Causes** | | 0.0 | 0 | 0.0 | 0 |
| Total Other causes | | 0.0 | 0 | 0.0 | 0 |
| Total CMS downtime | | 0.0 | 0 | 0.0 | 0 |
| [(Total CMS downtime)/(Total source operating time)]X100 (%) | | 0.00% | | 0.00% | |

Footnote 1 for, "Monitor Equipment Malfunctions, Non-Monitor Equipment Malfunctions, and Quality Assurance/Quality Control Calibrations": Except for actions which may have been previously reported according to 40 CFR 63.10(d)(5)(ii), actions taken in response to SSM events were consistent with the procedures specified in the SSM plan required by 40 CFR 63.6(e)(3). These actions were documented pursuant to 40 CFR 63.6(e)(3)(iii) and reported per 40 CFR 63.10(d)(5)(i).

EXPERA specialty solutions™

## DETAIL REPORT - Continuous Monitoring System Performance

**Thilmany Mill** | **Smelt Dissolving Tank 8** | **Report Run Date:** 4/20/2016 4:34 PM

**Reporting Period:** **From** 1/1/2016 **To** 4/1/2016

### CMS Performance Detail for SSM Events and Other Events

| Start Time | End Time | Duration (Hours) | Location | Trouble | Cause | Correction | Report Code |
|---|---|---|---|---|---|---|---|
| **Smelt Dissolving Tank 8** | | | | | | | |
| | | | SDT8 dP CMS | No Events | | | |
| | | | SDT8 Flow CMS | No Events | | | |

EXPERA specialty solutions

# SUMMARY REPORT - Gaseous and Opacity Excess Emissions

**Thilmany Mill**

## Smelt Dissolving Tank 10

**Reporting Period:** **From** 1/1/2016 **To** 4/1/2016

**Report Run Date** 4/20/2016 4:33 PM

| | |
|---|---|
| **Hazardous Air Pollutants (HAPS) Monitored:** | Particulate Matter (PM) emissions as a surrogate for HAP metals (Subpart MM, §63.860). |
| **Brief description of process unit:** | Molten inorganic kraft cooking chemicals (smelt) recovered by the No. 10 Recovery Furnace are dissolved in weak wash to produce Green Liquor. PM emissions are controlled by a Turbulaire scrubber. |

| **Emission Data Summary** | | | | |
|---|---|---|---|---|
| **Emission Point:** | SDT10 | | | |
| **Source Operating Time:** | 2128.7 Hours | | | |
| **Operating Parameter:** | dP | | Flow | |
| **Averaging Period:** | 3-hr Avg | | 3-hr Avg | |
| **Parameter Limit:** | 5.0 " H2O | | 35.0 gpm | |
| **Monitoring Exceedances In Reporting Period Due To:** | Duration Hours | Count No. | Duration Hours | Count No. |
| **a. Startup/Shutdown** | 0.0 | 0 | 0.0 | 0 |
| **b. Control Equipment Problems-Malfunction** | 0.0 | 0 | 0.0 | 0 |
| **c. Process Problems-Malfunction** | 0.0 | 0 | 0.0 | 0 |
| Total SSM monitoring exceedances | 0.0 | 0 | 0.0 | 0 |
| **d. Other Known Causes** | 0.0 | 0 | 0.0 | 0 |
| **e. Other Unknown Causes** | 0.0 | 0 | 0.0 | 0 |
| Total Other monitoring exceedances | 0.0 | 0 | 0.0 | 0 |
| [(Total Other monitoring exceedances)/(Total source operating time)]X100 (%) | 0.00% | | 0.00% | |
| Total monitoring exceedances | 0.0 | 0 | 0.0 | 0 |
| [(Total monitoring exceedances)/(Total source operating time)]X100 (%) | 0.00% | | 0.00% | |
| Number of 24 hour periods with one or more non-SSM monitoring exceedances | 0 | | | |

Footnote 1 for, "Startup/Shutdown, Control Equipment Problems, and Process Problems": Except for actions which may have been previously reported according to 40 CFR 63.10(d)(5)(ii), actions taken in response to SSM events were consistent with the procedures specified in the SSM plan required by 40 CFR 63.6(e)(3). These actions were documented pursuant to 40 CFR 63.6(e)(3)(iii) and reported per 40 CFR 63.10(d)(5)(i).

Footnote 2 for, "Number of 24-hour periods with one or more non-SSM monitoring exceedances": Periods of excess emission are not a violation of 40 CFR 63.862 provided the number of 3-hour parameter exceedances is not 6 or greater during the source operating time within a semi-annual period per 40 CFR 63.864(k)(2)(iii), excluding periods of startup, shutdown and malfunction [40 CFR 63.6(f)(1)]. No more than one exceedance shall be attributed to any 24-hour period per 40 CFR 63.864(k)(3).

EXPERA specialty solutions

# No Excess Emission Detail Report

**Thilmany Mill** | **Smelt Dissolving Tank 10** | **Report Run Date:** 4/20/2016 4:33 PM

**Reporting Period:** **From** 1/1/2016 **To** 4/1/2016

## No Excess Emission Events

| Start Time | End Time | Duration (Hours) | Location | Trouble | Cause | Correction | Report Code |
|---|---|---|---|---|---|---|---|
| **Smelt Dissolving Tank 10** | | | | | | | |
| | | | SDT10 dP EE | No Events | | | |
| | | | SDT10 Flow EE | No Events | | | |

EXPERA specialty solutions™

# SUMMARY REPORT - Continuous Monitoring System Performance

**Thilmany Mill** — **Smelt Dissolving Tank 10**

**Reporting Period:** **From** 1/1/2016 — **To** 4/1/2016

**Report Run Date** 4/21/2016 8:48 AM

| **CMS Performance Summary** | **Emission Point:** | SDT10 | | | |
|---|---|---|---|---|---|
| | **Source Operating Time:** | 2128.7 Hours | | | |
| | **Monitoring Equipment:** | dP | | Flow | |
| **CMS Downtime In Reporting Period Due To:** | | Duration Hours | Count No. | Duration Hours | Count No. |
| **a. Monitor Equipment Malfunctions** | | 0.0 | 0 | 0.0 | 0 |
| **b. Non-Monitor Equipment Malfunctions** | | 0.0 | 0 | 0.0 | 0 |
| **c. Quality Assurance/Quality Control Calibrations** | | 0.0 | 0 | 0.0 | 0 |
| Total malfunctions & QA/QC calibrations | | 0.0 | 0 | 0.0 | 0 |
| **d. Other Known Causes** | | 0.0 | 0 | 0.0 | 0 |
| **e. Other Unknown Causes** | | 0.0 | 0 | 0.0 | 0 |
| Total Other causes | | 0.0 | 0 | 0.0 | 0 |
| Total CMS downtime | | 0.0 | 0 | 0.0 | 0 |
| [(Total CMS downtime)/(Total source operating time)]X100 (%) | | 0.00% | | 0.00% | |

Footnote 1 for, "Monitor Equipment Malfunctions, Non-Monitor Equipment Malfunctions, and Quality Assurance/Quality Control Calibrations": Except for actions which may have been previously reported according to 40 CFR 63.10(d)(5)(ii), actions taken in response to SSM events were consistent with the procedures specified in the SSM plan required by 40 CFR 63.6(e)(3). These actions were documented pursuant to 40 CFR 63.6(e)(3)(iii) and reported per 40 CFR 63.10(d)(5)(i).

EXPERA specialty solutions

## DETAIL REPORT - Continuous Monitoring System Performance

**Thilmany Mill** | **Smelt Dissolving Tank 10** | **Report Run Date:** 4/21/2016 8:48 AM

**Reporting Period:** **From** 1/1/2016 **To** 4/1/2016

### CMS Performance Detail for SSM Events and Other Events

| Start Time | End Time | Duration (Hours) | Location | Trouble | Cause | Correction | Report Code |
|---|---|---|---|---|---|---|---|
| **Smelt Dissolving Tank 10** | | | | | | | |
| | | | SDT10 dP CMS | No Events | | | |
| | | | SDT10 Flow CMS | No Events | | | |

EXPERA specialty solutions™

# SUMMARY REPORT - Gaseous and Opacity Excess Emissions

## Thilmany Mill

## Smelt Dissolving Tank Bypass

**Reporting Period:** **From** 1/1/2016 **To** 4/1/2016

**Report Run Date** 4/20/2016 4:34 PM

| | |
|---|---|
| **Hazardous Air Pollutants (HAPS) Monitored:** | Particulate Matter (PM) emissions as a surrogate for HAP metals (Subpart MM, §63.860). |
| **Brief description of process unit:** | Molten inorganic kraft cooking chemicals (smelt) recovered by the Recovery Furnaces are dissolved in weak wash to produce Green Liquor. PM emissions are controlled by a Turbulaire scrubber. This report documents scrubber bypass emissions. |

| **Emission Data Summary** | **Emission Point:** | SDT10 Bypass | | SDT8 Bypass | |
|---|---|---|---|---|---|
| | **Source Operating Time:** | 2128.7 Hours | | 2114.3 Hours | |
| | **Operating Parameter:** | System Bypass | | System Bypass | |
| | **Averaging Period:** | Instantaneous | | Instantaneous | |
| | **Parameter Limit:** | Bypass Closed During Operation | | Bypass Closed During Operation | |
| **Monitoring Exceedances In Reporting Period Due To:** | | Duration Hours | Count No. | Duration Hours | Count No. |
| **a. Startup/Shutdown** | | 0.0 | 0 | 0.0 | 0 |
| **b. Control Equipment Problems-Malfunction** | | 0.0 | 0 | 0.0 | 0 |
| **c. Process Problems-Malfunction** | | 0.0 | 0 | 0.0 | 0 |
| Total SSM monitoring exceedances | | 0.0 | 0 | 0.0 | 0 |
| **d. Other Known Causes** | | 0.0 | 0 | 0.0 | 0 |
| **e. Other Unknown Causes** | | 0.0 | 1 | 0.0 | 0 |
| Total Other monitoring exceedances | | 0.0 | 1 | 0.0 | 0 |
| [(Total Other monitoring exceedances)/(Total source operating time)]X100 (%) | | 0.00% | | 0.00% | |
| Total monitoring exceedances | | 0.0 | 1 | 0.0 | 0 |
| [(Total monitoring exceedances)/(Total source operating time)]X100 (%) | | 0.00% | | 0.00% | |

Footnote 1 for, "Startup/Shutdown, Control Equipment Problems, and Process Problems": Except for actions which may have been previously reported according to 40 CFR 63.10(d)(5)(ii), actions taken in response to SSM events were consistent with the procedures specified in the SSM plan required by 40 CFR 63.6(e)(3). These actions were documented pursuant to 40 CFR 63.6(e)(3)(iii) and reported per 40 CFR 63.10(d)(5)(i).

EXPERA specialty solutions

# No Excess Emission Detail Report

**Thilmany Mill** — **Smelt Dissolving Tank Bypass** — **Report Run Date:** 4/20/2016 4:34 PM

**Reporting Period:** From 1/1/2016 To 4/1/2016

## No Excess Emission Events

| Start Time | End Time | Duration (Minutes) | Location | Trouble | Cause | Correction | Report Code |
|---|---|---|---|---|---|---|---|
| **Smelt Dissolving Tank Bypass** | | | | | | | |
| | | | SDT10 Bypass | No Events | | | |
| | | | SDT8 Bypass | No Events | | | |